Page 1

Thursday, November 04, 2010 11:06:27 AM Item ID: D3914-041 Accept Setup Start **Revision ID:** Stop Item Name: Long Basket Lid Assembly (350) Start Qty: 1.00 **Start Date:** 11/4/2010 **Cust Item ID:** Req'd Qty: 1.00 **Required Date:** 11/12/2010 **Customer:** Reference: Run Start Date: 10-11-01 Tooling: **Approvals:** Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Tool ID Reject Set Up/ Tool # Plan Accept Reject Insp. Work Center ID **Description** Qty **Run Hours** Code Qty Number Stamp **Draw Nbr Revision Nbr** D3914 В 100 Weld per dwg A/R S.S. rod Batch: 111585 0.00 Large Fab Large Fab 0.00 Memo Large Fab 1- assemble ribs, weld as per dwg D3914 using DT9607A 2- weld hinge (3) and Mounting brackets as per dwg D3914 ***inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***make sure to place mesh correctly on lid, check with label plate before tacking mesh*** 110 QC9- Inspect visual per QSI004- Fusion Welds 0.00

Quality Control

QC

Memo

0.00

									τ .	
W/O:			WO	RK ORDER CHANGE	ES					
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		 								
					1					
Part No	Part No: PAR #: Resolution:									
Resolu		solution:	Disposition	n:	QA: N/C	Closed: _		Date: _	· ·	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NO	CR)				
DATE	CTED	Description of NC		Corrective Action Section		Ver	ification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigi Da	1& _Տ ,	ection C	Chief Eng	QC Inspector	
									·	
•										
		· · · · · · · · · · · · · · · · · · ·								
		,								

Required Date: 11/12/2010

Thursday, November 04, 2010 11:06:27 AM

Item ID:

D3914-041

Accept

Setup Start

Stop



Revision ID:

Long Basket Lid Assembly (350) Item Name:

Start Date:

11/4/2010

Start Otv: 1.00

Req'd Oty: 1.00



Cust Item ID: Customer:

Reference:

Λ	nn	ras	, a l	٠.
- A	บบ	rov	a	S:

Process Plan:

Date:

Tooling:

Date:

Run Start



OC:

Date:

SPC (Y/N):

Date:

Stop

1 Bl 10-11-10.

Sequence ID/ Work Center ID

120

Operation

Description

OC6- Inspect dimensions to drawing

Set Up/ Run Hours

Tool ID

Tool # Plan Code Accept Reject Otv

Reject Number

Insp. Stamp

Memo

Oty

Quality Control

130

Powdercoat

Powder Coating

Black Sandtex(Ref:4.3.5.7) per QS1005 4.3

Memo

0.00

0.00

*** mask sides of hinge prior to powdercoat***
Start Time:

Oven Temperature:

Wing Walk as per dwg QSI005 4.4 Batch // 115 7-9700

10/11/10

Memo

0.00

- Mask data plate and apply wing walk on outside surface of mesh as per dwg

2- Install placard and label as per dwg

HandFinish

Hand Finishing

140

W/O:			WO	RK ORDER CHAN	IGES						
DATE	STEP	PRO	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No			Fault Category:			: Yes N	lo DQ				
Resolution		solution:	Disposition	1:	QA:	N/C Clo	sed:		Date:	<u> </u>	
NCR:		,	WORK ORDE	R NON-CONFOR	MANCE	(NCR)			the state of the s		
DATE	0.750	Description of NC		Section B		Verific	cation	Approval	Approval		
DAIE	STEP	Section A	Initial Chief Eng	Action Descriptio Chief Eng	n	Sign & Date		on C	Chief Eng	QC Inspector	
		T		-							

Work Order ID 63566

Thursday, November 04, 2010 11:06:27 AM



Page 3

Item ID:

D3914-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

11/4/2010

Start Oty: 1.00

Req'd Oty: 1.00 **Required Date: 11/12/2010**



Cust Item ID: Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Tool # Plan

Code

Start Run

Reject

Qty



Date:

SPC (Y/N):

Date:

Stop



Insp.

Sequence ID/ Work Center ID

150

Quality Control

Operation Description

OC3- Inspect Part Finish

Memo

Set Up/ **Run Hours**

0.00

0.00

Qty

Accept

Number Stamp

Reject

160

Packaging Packaging

Memo

170

Quality Control

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

0.00

Memo

0.00

Dail Ac	ospace Liu							,
W/O:			WORK ORDER CHANGES					
DATE	STEP	PF	ROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-		
Part No	:	PAR #:	Fault Category:	NCR: Y	es No DQ	A:	Date: _	
	Resolution	1:	Disposition:	QA: N/0	Closed:		Date: _	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B									
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector					
						:	ļ Į						
				W		·							

Picklist Print

Thursday, November 04, 2010 11:06:31 AM

Work Order ID: 63566

Parent Item:

D3914-041

Parent Item Name: Lon, Basket Lid Assembly (350)



Sta: . Date: 11/4/2010

Required Late: 11/12/2010

Page 1

Start Qty: 1.00

Required Qty: 1.00


Comments:

IPP Rev:A new issue DD 10.03.19 verified by:EC

as per dw

:A nev	w issue DD	10.03.19 verified by:EC	IPP Rev:B
vg revB	DD 10.08	.18 verified by:EC	

		is per dwg fevb Di	D 10.08.18 VEIIII	cu by.1										
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
/	D2581 Mounting Bracket		Manufactured	No			100	Each	23.0000	2	2	p/	10.4.	09
					Locatio	<u>ın</u>	Loc ·	<u>Oty</u>	Loc Code		•	•		
					WA			23				_		
						60470		3		<i>(</i>	2/	_	^	
						61953		20		_	\leq	- //	7	
	D3914-1	 	Manufactured	No			100	Each	4.0000	2	2		1	
(C p	110	10.09
					Locatio	<u>n</u>	Loc	<u>Oty</u>	Loc Code			/		
					WA			4				_		
						60703		4		+	2)	- /)	
/	D3914-7		Manufactured	No			100	Each	4.0000	2	$\overline{2}$. /	
	Rib											_C/	110.	14.09
	Kib				Location	<u>on</u>	Loc	<u>Oty</u>	Loc Code			V		
					WA			4						
						60676		4		_	<u>a</u>	_	\sim	
,	D4016-3		Manufactured	No			100	Each	7.0000	3	3	,	///	
	Hinge Half, Lid											(-	pl/	0.10.00
					Locatio	<u>on</u>	<u>Loc</u>	<u>Qty</u>	Loc Code					
					ST116			6		_				
						60723		6		يَ	(3X	<u>2</u>)		
											<u> </u>			





W/O:	•		WO	RK ORDER CHANG	ES							
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							•					
Part No			Fault Category: NC			NCR: Yes No DQA: Date:						
	Resolution:		Disposition	:	_ QA: N/C	Clos	ed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)						
DATE	STEP	Description of NC Section A	Initial	Action Description	cription Sign &			cation on C	Approval Chief Eng	Approval QC Inspector		
			Chief Eng	Chief Eng		ate						
							:					

Thursday, November 04, 2010 11:06:31 AM

Work Order ID: 63566 Parent Item:

D3914-041

Parent Item Name: Lc & Basket Lid Assembly (350)

No

WA

Location

Location

60546 61066

WA

60643 60733

WA

D4018-5

Manufactured

100

Each 15.0000

Loc Code

Loc Code

Starí Date: 11/4/2010 Start Qty: 1.00

Required Jate: 11/12/2010

Required Qty: 1.00

D4020-5 Mesh (350 Basket Long, Lid)

Manufactured No Location Loc Oty 15 59929 15 100

Each 3.0000

D4021-3 Data Plate

Manufactured No

Loc Qty 3 2 100 Each

Loc Qty

2

4.0000

Loc Code

D4035-041

Lid Rib Assembly, Fwd (350 Basket)

Manufactured No Location Loc Qty WA 56050 59987 60734 2 100 Each

3.0000

Loc Code

W/O:			WC	RK ORDER CHANG	ES				•			
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	!											
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:							
	R	esolution:	Disposition	n:	_ QA: N/C Q	losed:		Date: _				
NCR:			WORK ORD	R NON-CONFORMA	NCE (NC	R)						
DATE	OTED	Description of NC Corrective Action			on B	Verifi	cation	Approvai	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sec	tion C	Chief Eng	QC Inspector			
								ę.				
•												
]												
,												
						,						

Picklist Print

Thursday, November 04, 2010 11:C6:31 AM

Page 3

Work Order ID: 63566

Parent Item:

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)



St...t Date: 11/4/2010

Required Date: 11/12/2010

Start Qty: 1.00

Required Qty: 1.00

D4035-043

Lid Rib Assembly, Aft (350 Basket)

Manufactured No 100

140

Each

3.0000

Loc Code

Manufactured

Location WA

> 60475 61067

Loc Qty

1 2

Each

0.0000

D2728-3


Dart Logo label

M115050




W/O:			WORK ORDER CHANGES						
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Category:	NCR : Ye	s No DQ	A:	Date:		
	Resolution	 :	Disposition:	QA: N/C	Closed:		Date:		


NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	T	Description of NC		Corrective Action Section B							
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	ription Sign & Date		Approval Chief Eng	Approval QC Inspector			
		Will be provided the second		· · · · · · · · · · · · · · · · · · ·							




W/O:			W	ORK ORDER CHANGI	ES					
DATE	STEP	PRO	CEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
·										
Part No:		PAR #:	Fault Cate	egory:	NCR: Yes	No DO	QA:	Date: _		
Resoluti		solution:	Disposition	on:	QA: N/C Closed: Date:					
NCR:		V	ORK ORD	ER NON-CONFORMA	NCE (NC	R)				
DATE	STEP	Description of NC		Corrective Action Section		Verif	Verification	Approval Chief Eng	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	ction C		QC Inspector	
•					ŀ					
]									



W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:						
Resolution:			Disposition	_ QA: N/C Clo	QA: N/C Closed: Date:						
NCR:		•	WORK ORD	ER NON-CONFORMA	NCE (NCR)						
DATE STEP	STEP	Description of NC	Corrective Action Section B			Verification		Approval			
	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				



											
W/O:			WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No		DAR #•	Fault Cateo	MORV.	NCB: Vas	No DO	Δ.	Date:			
Part No: PAR #: Resolution:			Disposition:								
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)		<u> </u>			
	STEP	Description of NC Section A			on B	Verifi	cation	Approval	Approval		
DATE			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector		



Dart Ae	rospace	: Ltd								7
W/O:				WORK ORDER	CHANGES					
DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										` .
		•	PAR #: Fault Category:		NCR: Yes No DQA:			Date:		
			Disposition:		QA: N/C Closed:			Date: _	Date:	
NCR:				WORK ORDER NON-CO	NFORMANCE	(NC	R)			

NCR:		,	WORK ORDE	ER NON-CONFORMAN	CE (NCR)	_		
DATE		Description of NC Section A		Verification	Ammayal	Annuaral		
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
			<u> </u>					
							ŕ	